

**ACTON •  
MICKELSON •  
ENVIRONMENTAL, INC.**

5175 Hillsdale Circle #100  
El Dorado Hills, CA 95762

**LOG OF BORING**

**MW-5.11**

Facility: G-P Fort Bragg

Address: 90 W. Redwood Ave.  
Fort Bragg, CA

AME Project No.: 16017.08

Area No./ Description: Parcel 5, Mobile Equipment Shop, West of Building

Page 1 of 1

Drilling Company: RSI  
Drilled By: Don Jenkins  
Drilling Method: Hollow Stem  
Boring Diameter: 8"  
Sampling Method: California Modified Split Spoon Sampler and Standard Penetration Test (SPT)




Location (East/North):  
Ground Surface Elevation:  
Water Depth (Date, Time): 5' (11/16/05 0805)  
Casing Elevation:  
Total Depth (feet): 19' BGS  
Weather: clear/cool

Drilling Started: 11/16/05 0750  
Drilling Finished: 11/16/05 0840

Logged By: J.D. Matthey, R.G., C.E.G  
Checked By:

Source: Original field notes

PID/FID: PID

DEPTH (feet)	SAMPLE		BLOW COUNTS		SOIL DESCRIPTION	GRAPHIC LOG	SOIL CLASS	WELL GRAPHIC	COMMENTS	FIELD PID READING (ppm)	
	INTERVAL	SAMPLE ID	BLOWS/6 IN. (N)	IN. RECVD					DRILLING RATE AND CONDITIONS, WATER DEPTH, BACKFILL		
0		MW-5.11-3	50	6	FILL - SILTY GRAVEL (GM), gray (2.5Y 6/1), Dense, Moist, 70% gravel, 2 cm clast, 20% fine to medium sand, 10% fines.		GM		No Sample Recovered (Cobbles)	0	
			20-20-19 (39)	12	FILL - SILTY SAND (SM), very dark grayish brown (2.5Y 3/2), Medium Dense, Moist, 10% fine gravel, 0.5 cm clast, 70% fine to medium sand, 20% fines.						SM
5			9-6-5 (11)	14	light gray (2.5Y 7/1), Medium Dense, Wet, Fill?, Strong Hydrocarbon Odor 90% fine sand, 10% fines.						
10			10-21-41 (62)	14	Band of Brown Staining.						
15			12-13-21 (34)	17	Sheen on Cuttings, Flowing Sands. Wood Fragment Oriented at 45 Deg. (Redwood Bark).						
									Boring Terminated Total Depth = 19'		

LOG OF BORING 1601708.GPJ ACTON.GDT 3/17/06